

Bridge Inspection Form

Struct. ID 03-06 B0400



Description

East railing, loose end cap

Elem Grp/Class	Barriers/Railing Systems
Elem Type	4 Rail Metal Railing - Aluminum
Sub Element	
Material Type	Aluminium
Locator	East
Defect Descript1	Fair condition
Defect Descript2	
Defect	
Other	

File Name DSCN4167.JPG



Description

East railing, top rail separated

Elem Grp/Class	Barriers/Railing Systems
Elem Type	4 Rail Metal Railing - Aluminum
Sub Element	
Material Type	Aluminium
Locator	East
Defect Descript1	Fair condition
Defect Descript2	
Defect	
Other	

File Name DSCN4168.JPG

York Region

Bridge Inspection Form

Struct. ID 03-06 B0400



Description

East elevation, general photo

Elem Grp/Class

Elem Type

Sub Element

Material Type

Locator

Defect Descript1

Defect Descript2

Defect

Other

File Name DSCN4170.JPG



Description

Spall, exposed rebar

Elem Grp/Class

Elem Type

Sub Element

Material Type

Locator

Defect Descript1

Defect Descript2

Defect

Other

Beams/MLE's/Girders

Box/trapezoidal

End

Precast concrete

North

File Name DSCN4175.JPG

York Region Bridge Inspection Form

Struct. ID 03-06 B0400



Description

Delamination on box girder

Elem Grp/Class	Beams/ML'E's/Girders
Elem Type	Box/trapezoidal
Sub Element	End
Material Type	Precast concrete
Locator	
Defect Descript1	Poor condition
Defect Descript2	
Defect	Delamination
Other	

File Name DSCN4179.JPG



Description

Soffit general photo

Elem Grp/Class	Beams/ML'E's/Girders
Elem Type	Box/trapezoidal
Sub Element	Middle
Material Type	Precast concrete
Locator	
Defect Descript1	
Defect Descript2	
Defect	
Other	

File Name DSCN4182.JPG

York Region

Bridge Inspection Form

Struct. ID 03-06 B0400



Description

Spalls with exposed rebar

Elem Grp/Class	Abutments/Ballast walls
Elem Type	
Sub Element	
Material Type	Cast-in-place concrete
Locator	North
Defect Descript1	Poor condition
Defect Descript2	
Defect	Spalling
Other	reinforcement

File Name DSCN4186.JPG



Description

East elevation, general photo

Elem Grp/Class	
Elem Type	
Sub Element	
Material Type	
Locator	East
Defect Descript1	
Defect Descript2	
Defect	
Other	

File Name DSCN4188.JPG

York Region

Bridge Inspection Form

Struct. ID 03-06 B0400



Description

West girder, spalls with exposed rebar

Elem Grp/Class	Beams/ML's/Girders
Elem Type	Box/trapezoidal
Sub Element	End
Material Type	Precast concrete
Locator	West
Defect Descript1	
Defect Descript2	
Defect	
Other	

File Name DSCN4197.JPG



Description

Soffit exterior, delamination

Elem Grp/Class	Barriers/Barrier/Parapet Walls
Elem Type	Other
Sub Element	Exterior
Material Type	Cast-in-place concrete
Locator	East
Defect Descript1	
Defect Descript2	
Defect	
Other	

File Name DSCN4199.JPG

Bridge Inspection Form

Struct. ID 03-06 B0400



Description

Southbound lane, cracking, filled pot holes

Elem Grp/Class	Decks/Wearing surface
Elem Type	
Sub Element	
Material Type	Asphalt
Locator	Middle
Defect Descript1	
Defect Descript2	
Defect	Cracking
Other	

File Name DSCN4205.JPG



York Region

Bridge Inspection Form

Struct. ID	03-06 B0400
------------	-------------