

Bathurst Street

Intersection Improvements at Davis Drive

Northbound Bathurst Street to westbound Davis Drive double left turn lanes.

Eastbound Davis Drive to northbound Bathurst Street double left turn lanes.

Installing street lighting, on-street bike lanes, sidewalks and new transit stops.

Reason:

To expand the transportation system to accommodate growth in travel demand resulting from development.

Current Status:

Complete

Road, Municipality:

Bathurst Street, Newmarket and King

Project Number:

84860

Contact:

Jamal Ahmed
1-877-464-9675 ext. 75955
jamal.ahmed@york.ca

