

Initial Report

Premise/Facility under investigation (name and address)

**Rejuuv Medispa
1009-32 South Unionville Ave.
Markham, Ontario
L3R 1J5**

Type of Premises/Facility

Medispa

Date Board of Health became aware of IPAC lapse (yyyy/mm/dd)

2018/11/05

Date of Initial Report posting (yyyy/mm/dd)

2019/06/20

Date of Initial Report update(s) (if applicable) (yyyy/mm/dd)

How the IPAC lapse was identified

Referral from College of Physicians and Surgeons of Ontario

Summary Description of the IPAC Lapse

During an inspection on Nov. 5, 2018, York Region Public Health noted the following: manual cleaning and proper labelling of critical medical equipment/instruments were not being done appropriately prior to being transported to a location outside of York Region for full reprocessing where reprocessing did not meet Provincial Infectious Diseases Advisory Committee (PIDAC) best practices for sterilization of reusable medical equipment/instruments.

IPAC Lapse Investigation

	Yes	No	N/A	Please provide further details/steps
Did the IPAC lapse involve a member of a regulatory college?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
If yes, was the issue referred to the regulatory college?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Were any corrective measures recommended and/or implemented?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

Please provide further details/steps

An inspection was conducted on November 5, 2018. The medispa must ensure the following:

- Prior to resuming use of reusable medical equipment/instruments:
 - Use a dedicated sink for manual cleaning of medical equipment/instruments
 - Use an enzymatic solution for cleaning medical equipment/instruments prior to sterilization
 - Medical equipment/instruments are to be in the open position for manual cleaning
 - Use a brush(es) for manual cleaning of medical equipment/instruments that are inspected frequently; high-level disinfect or dispose of at end of day
 - Medical equipment/instruments that has undergone a manual cleaning step prior to further reprocessing offsite is to be placed in a leak proof container with a lid and labelled appropriately for transport
 - Ensure offsite location is meeting PIDAC requirements for sterilization of reusable medical equipment/instruments
 - Alternatively, the operator can use sterile, single-use medical equipment/instruments and discard after use

Date any order(s) or directive(s) were issued to the owner/operator (if applicable) (yyyy/mm/dd)

Initial Report Comments and Contact Information

Any additional Comments: (Please do not include any personal information or personal health information)

An inspection report was provided to the clinic on November 5, 2018 outlining corrective measures to be implemented. The operator was educated on site during the inspection and instructed to use proper infection prevention and control practices.



York Region Infection Prevention And Control Lapse Report

If you have any further questions, please contact
Health Connection

Telephone Number

1-800-361-5653

Email Address

Health.inspectors@york.ca

Final Report

Date of Final Report posting (yyyy/mm/dd)

2019/06/20

Date any order(s) or directive(s) were issued to the owner/operator (if applicable) (yyyy/mm/dd)

Brief description of corrective measures taken

Operator has sterile, single-use medical equipment/instruments on-site. Should the Premise resume use of reusable medical equipment/instruments operator will ensure they have been reprocessed in accordance with PIDAC best for sterilization of reusable medical equipment/instruments.

Date of all corrective measures were confirmed to have been completed (yyyy/mm/dd)

2019/02/21

Final Report Comments and Contact Information

Any Additional Comments:

If you have any further questions, please contact

Health Connection

Telephone Number

1-800-361-5653

Email Address

Health.inspectors@york.ca