

York Region Infection Prevention And Control Lapse Report

Initial Report							
Premise/Facility under investigation (name and address)							
York Region Sleep Disorders Centre							
Unit 300 – 13291 Yonge Street							
Richmond Hill, Ontario L4E 4L6							
Type of Premises/Facility							
Sleep Disorders							
Date Board of Health became aware of IPAC lapse			Date of Initial Report posting (yyyy/mm/dd)				
(yyyy/mm/dd)							
2021/07/08		2021/09/08					
Date of Initial Report update(s) (if applicable) (yyyy/mm/dd)		How the IPAC lapse was identified Complaint					
On July 08, 2021 York Region Public Health conducted at medical equipment/devices. Chemical product used for di appropriate: chemical product did not have Health Canada to manufacturer's instructions for use, and was not compared one-way work flow from dirty to clean to prevent cross-concleaning of medical instruments were not replaced or ade available for staff in the reprocessing area; clean and dising contamination; a log of the equipment that received disinferences.	sinfection a Medicatible wintamination quality nfected	on call thu tion tion rep eq	of multi-u Device L medical e n of mult processed uipment	ise sem icense, equipme i-use m d; perso was no	ni-critical medical equipment/devices was not Class 2; was not prepared and used according ent/devices being reprocessed. There was no edical instruments; brushes used for manual anal protective equipment (PPE) was not		
IPAC Lapse Investigation	Yes		No	N/A	Please provide further details/steps		
Did the IPAC lapse involve a member of a regulatory college?	\boxtimes						
If yes, was the issue referred to the regulatory college?	\boxtimes				College of Physicians and Surgeons of Ontario		
Were any corrective measures recommended and/or implemented?	\boxtimes						
Please provide further details/steps	Corre	ctiv	ve meas	III'AS'			
r lease provide further details/steps	•	CLI			ering any services at this premise whereby		
	,				ruments are required to be high-level disinfected		
	•	Discontinue the use of any multi-use equipment/instruments that were disinfected using inappropriate high-level disinfection					
			process	and in	appropriate chemical product.		
	The clinic must ensure the following:						
		 Chemical products used for high-level disinfection have Health 					
		Canada Medical Device License, Class 2; and are used					
		 according to manufacturer's instructions for use Minimum effective concentration testing of the high-level 					
		disinfectant solution is monitored and logged before each					
		 medical device is processed for manual high-level disinfection. High level disinfectant test strips specific to the product are used 					
		and checked for accuracy when each test strip bottle is opened.					
	•		Multi-us	se semi	-critical medical equipment (e.g. masks,		
				nnection tubes) receive at a minimum high-level disinfection in			
		accordance with the equipment/devices manufacturer's instruction for use.					
	 Newly purchased, non-sterile critical and semi critical medical 						
	equipment/devices are inspected and reprocessed prior to use,						
	according to their intended use, as per manufacturer's instructions for use.						
	•	 Ensure brushes used for manual cleaning of medical 					
		equipment/instruments are inspected frequently; high-level disinfected or disposed of at end of day.					
					the equipment that received high-level		
			disinfec	•			



York Region Infection Prevention And Control Lapse Report

IPAC Lapse Investigation	Yes	No	N/A	Please provide further details/steps
	•	receivir packag workflo prevent Clean a stored i contam which h There i includir equipm are kep Work s seamle cleaned prepare use. Alcohol hygiene PPE is	ng, cleaning, high wiften from the cross of and disining a manination have not on the control of	processing area is separated into distinct areas for hing and decontamination, preparation and in-level disinfection, and storage. A one-way dirty to clean is established and maintained to contamination. Infected equipment/devices are transported and inner that prevents their damage and medical interprocessing area are flat, cut-resistant, composed of non-porous material that can be exceeded, and dried. In order to the prevents their damage and readily accessible in the reprocessing area are and readily accessible in the reprocessing area are, gown, mask, eye protection)
Date any order(s) or directive(s) were issued to the owner 2021/07/08, 2021/07/15.	er/operato			
2021/07/00, 2021/07/13.				
Initial Papart Comments and Contact Infor	mation			
Initial Report Comments and Contact Informany additional Comments: (Please do not include any performance) York Region Public Health provided an inspection rep	ersonal in			-
Any additional Comments: (Please do not include any per York Region Public Health provided an inspection repute implemented. The operator was educated on site of prevention and control practices. Follow-up written O July 15, 2021. A re-inspection was conducted on July measures had been implemented. If you have any further questions, please contact	ersonal in oort to the luring the rder und	e premise inspect er the He	e on Ju ion and alth Pr	ly 08, 2021 outlining corrective measures to was instructed to use proper infection otection and Promotion Act was issued on
Any additional Comments: (Please do not include any per York Region Public Health provided an inspection repute implemented. The operator was educated on site of prevention and control practices. Follow-up written O July 15, 2021. A re-inspection was conducted on July measures had been implemented. If you have any further questions, please contact Health Connection	ersonal in port to the luring the rder und 15, 2021	e premiso e inspect er the He and July	e on Ju ion and alth Pr	ly 08, 2021 outlining corrective measures to was instructed to use proper infection otection and Promotion Act was issued on
Any additional Comments: (Please do not include any per York Region Public Health provided an inspection repute implemented. The operator was educated on site of prevention and control practices. Follow-up written O July 15, 2021. A re-inspection was conducted on July measures had been implemented. If you have any further questions, please contact Health Connection Telephone Number	ersonal in port to the luring the rder und 15, 2021	e premise e inspect er the He and July	e on Ju ion and ealth Pro 21, 20	ly 08, 2021 outlining corrective measures to was instructed to use proper infection otection and Promotion Act was issued on 21 where it was noted that all corrective
Any additional Comments: (Please do not include any per York Region Public Health provided an inspection repute implemented. The operator was educated on site of prevention and control practices. Follow-up written O July 15, 2021. A re-inspection was conducted on July measures had been implemented. If you have any further questions, please contact Health Connection	ersonal in port to the luring the rder und 15, 2021	e premiso e inspect er the He and July	e on Ju ion and ealth Pro 21, 20	ly 08, 2021 outlining corrective measures to was instructed to use proper infection otection and Promotion Act was issued on 21 where it was noted that all corrective
Any additional Comments: (Please do not include any per York Region Public Health provided an inspection repute implemented. The operator was educated on site of prevention and control practices. Follow-up written O July 15, 2021. A re-inspection was conducted on July measures had been implemented. If you have any further questions, please contact Health Connection Telephone Number	ersonal in port to the luring the rder und 15, 2021	e premise e inspect er the He and July	e on Ju ion and ealth Pro 21, 20	ly 08, 2021 outlining corrective measures to was instructed to use proper infection otection and Promotion Act was issued on 21 where it was noted that all corrective
Any additional Comments: (Please do not include any per York Region Public Health provided an inspection repute implemented. The operator was educated on site of prevention and control practices. Follow-up written O July 15, 2021. A re-inspection was conducted on July measures had been implemented. If you have any further questions, please contact Health Connection Telephone Number 1-800-361-5653	ersonal in port to the luring the rder und 15, 2021	e premise e inspect er the He and July	e on Ju ion and ealth Pro 21, 20	ly 08, 2021 outlining corrective measures to was instructed to use proper infection otection and Promotion Act was issued on 21 where it was noted that all corrective
Any additional Comments: (Please do not include any per York Region Public Health provided an inspection repute implemented. The operator was educated on site of prevention and control practices. Follow-up written O July 15, 2021. A re-inspection was conducted on July measures had been implemented. If you have any further questions, please contact Health Connection Telephone Number 1-800-361-5653 Final Report Date of Final Report posting (yyyy/mm/dd)	ersonal in port to the luring the rder und 15, 2021	e premise e inspect er the He and July Address	e on Ju ion and ealth Pro 1 21, 202	ly 08, 2021 outlining corrective measures to was instructed to use proper infection otection and Promotion Act was issued on 21 where it was noted that all corrective
Any additional Comments: (Please do not include any per York Region Public Health provided an inspection repute implemented. The operator was educated on site of prevention and control practices. Follow-up written O July 15, 2021. A re-inspection was conducted on July measures had been implemented. If you have any further questions, please contact Health Connection Telephone Number 1-800-361-5653 Final Report Date of Final Report posting (yyyy/mm/dd) 2021/09/08 Date any order(s) or directive(s) were issued to the own.	ersonal in port to the luring the rder und 15, 2021	e premise e inspect er the He and July Address	e on Ju ion and ealth Pro 1 21, 202	ly 08, 2021 outlining corrective measures to was instructed to use proper infection otection and Promotion Act was issued on 21 where it was noted that all corrective
Any additional Comments: (Please do not include any per York Region Public Health provided an inspection repute implemented. The operator was educated on site of prevention and control practices. Follow-up written O July 15, 2021. A re-inspection was conducted on July measures had been implemented. If you have any further questions, please contact Health Connection Telephone Number 1-800-361-5653 Final Report Date of Final Report posting (yyyy/mm/dd) 2021/09/08 Date any order(s) or directive(s) were issued to the own July 15, 2021	ersonal in port to the luring the rder und 15, 2021 Email A Health	e premise e inspect er the He and July Address .inspector	e on Ju ion and ealth Pro 21, 202 rs@york	ly 08, 2021 outlining corrective measures to was instructed to use proper infection otection and Promotion Act was issued on 21 where it was noted that all corrective
Any additional Comments: (Please do not include any per York Region Public Health provided an inspection rep be implemented. The operator was educated on site of prevention and control practices. Follow-up written O July 15, 2021. A re-inspection was conducted on July measures had been implemented. If you have any further questions, please contact Health Connection Telephone Number 1-800-361-5653 Final Report Date of Final Report posting (yyyy/mm/dd) 2021/09/08 Date any order(s) or directive(s) were issued to the own July 15, 2021 Brief description of corrective measures taken Date of all corrective measures were confirmed to have	ersonal in port to the luring the rder und 15, 2021 Email A Health er/operato	e premise e inspect er the He and July Address .inspector	e on Ju ion and ealth Pro 21, 202 rs@york	ly 08, 2021 outlining corrective measures to was instructed to use proper infection otection and Promotion Act was issued on 21 where it was noted that all corrective
Any additional Comments: (Please do not include any per York Region Public Health provided an inspection repute implemented. The operator was educated on site of prevention and control practices. Follow-up written O July 15, 2021. A re-inspection was conducted on July measures had been implemented. If you have any further questions, please contact Health Connection Telephone Number 1-800-361-5653 Final Report Date of Final Report posting (yyyy/mm/dd) 2021/09/08 Date any order(s) or directive(s) were issued to the own July 15, 2021 Brief description of corrective measures taken Date of all corrective measures were confirmed to have July 15, 2021 and July 21, 2021	ersonal in port to the luring the rder und 15, 2021 Email / Health er/operator been commation	e premise inspecte inspecte er the He and July Address Linspector Or (if applied (year)	e on Juion and ealth Provided to 21, 200	ly 08, 2021 outlining corrective measures to was instructed to use proper infection of otection and Promotion Act was issued on 21 where it was noted that all corrective
Any additional Comments: (Please do not include any per York Region Public Health provided an inspection repute implemented. The operator was educated on site of prevention and control practices. Follow-up written O July 15, 2021. A re-inspection was conducted on July measures had been implemented. If you have any further questions, please contact Health Connection Telephone Number 1-800-361-5653 Final Report Date of Final Report posting (yyyy/mm/dd) 2021/09/08 Date any order(s) or directive(s) were issued to the own July 15, 2021 Brief description of corrective measures taken Date of all corrective measures were confirmed to have July 15, 2021 and July 21, 2021 Final Report Comments and Contact Inform	ersonal in port to the luring the rder und 15, 2021 Email / Health er/operator been commation	e premise inspecte inspecte er the He and July Address Linspector Or (if applied (year)	e on Juion and ealth Provided to 21, 200	ly 08, 2021 outlining corrective measures to was instructed to use proper infection of otection and Promotion Act was issued on 21 where it was noted that all corrective
Any additional Comments: (Please do not include any per York Region Public Health provided an inspection rep be implemented. The operator was educated on site of prevention and control practices. Follow-up written O July 15, 2021. A re-inspection was conducted on July measures had been implemented. If you have any further questions, please contact Health Connection Telephone Number 1-800-361-5653 Final Report Date of Final Report posting (yyyy/mm/dd) 2021/09/08 Date any order(s) or directive(s) were issued to the own July 15, 2021 Brief description of corrective measures taken Date of all corrective measures were confirmed to have July 15, 2021 and July 21, 2021 Final Report Comments and Contact Inform Any Additional Comments: (Please do not include any pull you have any further questions, please contact	ersonal in port to the luring the rder und 15, 2021 Email / Health er/operator been comparisonal in the properator	e premise inspecte inspecte er the He and July Address Linspector Or (if applied (year)	e on Ju ion and ealth Pro 21, 202 rs@york icable) (yyyy/mm	ly 08, 2021 outlining corrective measures to was instructed to use proper infection of otection and Promotion Act was issued on 21 where it was noted that all corrective