

York Region Infection Prevention And Control Lapse Report

Initial Report					
Premise/Facility under investigation (name and address))				
Dr. A. Hirtenfeld					
204-13270 Young St.					
Richmond Hill, Ontario					
L4E 2T2					
Type of Premises/Facility Medical Clinic					
Date Board of Health became aware of IPAC lapse		Date	Date of Initial Report posting (yyyy/mm/dd)		
(yyyy/mm/dd)					
2018/07/11			2019/06/20		
Date of Initial Report update(s) (if applicable) (yyyy/mm/dd)			How the IPAC lapse was identified Complaint		
Summary Description of the IPAC Lapse					
IPAC Lapse Investigation	Yes	No	N/A	Please provide further details/steps	
Did the IPAC lapse involve a member of a regulatory college?	X			College of Physicians and Surgeons of Ontario	
If yes, was the issue referred to the regulatory college?	X				
Were any corrective measures recommended and/or implemented?	X				
Please provide further details/steps An inspection was conducted on July 11, 2018. The clinic mensure the following:					
	 Provide and wear personal protective equipment (e.g., gloves, gown, mask, eye protection) during manual cleaning of medical equipment/instruments as appropriate for any procedures that are likely to result in exposure to splashes or sprays of blood or other body fluids Provide a dedicated hand washing sink and/or alcohol-based hand rub in the reprocessing area Provide and use an enzymatic solution for manual cleaning of medical equipment/instruments prior to disinfection Follow the manufacturer's instructions for use (MIFU) of the BM 28 Plus disinfectant Monitor and log efficacy of high-level disinfectant (HLD) with appropriate test strips as per MIFU Maintain a log of medical equipment/instruments that receive HLD 				
are sterilized using an approved steriliz Provincial Infectious Diseases Advisory				se critical instruments are used on-site that they napproved sterilization process as per the Diseases Advisory Committee (PIDAC) Best g, Disinfection and Sterilization of Medical nall Health Care Settings, May 2013	
Date any order(s) or directive(s) were issued to the own	ner/operat	or (if app	licable)	(yyyy/mm/dd)	
Initial Report Comments and Contact Information					
Any additional Comments: (Please do not include any personal information or personal health information)					
An inspection report was provided to the clinic on July 11, 2018 outlining corrective measures to be implemented. The operator was educated on site during the inspection and instructed to use proper infection prevention and control practices. A re-inspection will be conducted to ensure corrective measures have been implemented.					

If you have any further questions, please contact Health Connection



York Region Infection Prevention And Control Lapse Report

Telephone Number 1-800-361-5653

Email Address

Health.inspectors@york.ca

Final Report

Date of Final Report posting (yyyy/mm/dd)

2019/06/20

Date any order(s) or directive(s) were issued to the owner/operator (if applicable) (yyyy/mm/dd)

Brief description of corrective measures taken

A re-inspection was conducted August 23, 2018 where it was noted by York Region Public Health that all corrective measures have been put into place. Operator was advised that if critical instruments are to be used in the future they must be single-use disposable or sterilized in accordance with PIDAC best practices.

Date of all corrective measures were confirmed to have been completed (yyyy/mm/dd) 2018/08/23

Final Report Comments and Contact Information

Any Additional Comments: (Please do not include any personal information or personal health information)

If you have any further questions, please contact

Health Connection

Telephone Number Email Address
1-800-361-5653 Health.inspectors@york.ca