



MORRISON HERSHFIELD

FINAL REPORT

Teston Road Area Transportation Improvements Individual Environmental Assessment

Phase One Environmental Site Assessment, Property 8, Teston Road, Maple, Ontario

Presented to:

Praveen John, P.Eng.
Senior Project Manager
The Regional Municipality of York

17250 Yonge Street
Newmarket, Ontario

Report No. 190261800

October 11, 2023

\\EGNYTDRIVE\IMH CLOUD\PROJ\2019\190261800-P-19-218-TESTON ROAD IEA\08.
WORKING\CONTAMINATION-WASTE\PHASE ONE ESAS\PHASE ONE ESA_PROPERTY
8\FINAL_PHASEONEESA_PROPERTY8_OCT 11_23.DOCX

TABLE OF CONTENTS

1.	EXECUTIVE SUMMARY	1
2.	INTRODUCTION	3
2.1	Phase One Property Information	3
3.	SCOPE OF INVESTIGATION	4
4.	RECORDS REVIEW	6
4.1	General	6
4.1.1	Phase One Study Area	6
4.1.2	First Developed Use	6
4.1.3	Fire Insurance Plans	6
4.1.4	City Directories	6
4.1.5	Environmental Reports	7
4.2	Environmental Source Information	7
4.2.1	Environmental Databases	7
4.2.2	Municipal Records	9
4.2.3	Ontario Ministry of the Environment, Conservation and Parks Documentation	10
4.2.4	Technical Standards & Safety Authority	10
4.3	Physical Setting Sources	10
4.3.1	Aerial Photographs	10
4.3.2	Topography, Hydrology and Geology	12
4.3.3	Fill Materials	13
4.3.4	Water Bodies and Areas of Natural Significance	13
4.3.5	Well Records	13
4.3.6	Site Operating Records	14
5.	INTERVIEWS	15

6.	SITE RECONNAISSANCE	16
6.1	General Requirements	16
6.2	Specific Observations at the Phase One Property	16
6.2.1	Layout, Tanks, Potable Water Sources	16
6.2.2	Buildings and Structures	16
6.2.3	Utilities	16
6.2.4	Wells, Sewage Works, Ground Surface and Railway Lines	16
6.2.5	Land (Signs of Contamination)	17
6.2.6	Special Attention Substances	17
6.3	Enhanced Investigation Property	17
6.4	Observations Within the Phase One Study Area	17
6.5	Written Description of Investigation	18
7.	REVIEW AND EVALUATION OF INFORMATION	19
7.1	Current and Past Uses of Phase One Property	19
7.2	Potentially Contaminating Activity	20
7.2.1	Phase One Property	20
7.2.2	Phase One Study Area	20
7.3	Areas of Potential Environmental Concern	20
7.4	Phase One Conceptual Site Model	21
8.	CONCLUSIONS	23
8.1	Whether a Phase Two ESA is Required Before Record of Site Condition Submitted	23
8.2	Record of Site Condition Based on Phase One Environmental Site Assessment Alone	23
8.3	Qualifications of Assessors	23
8.4	Signatures	24
9.	LIMITATIONS AND USE OF REPORT	25



10. REFERENCES	26
----------------	----

LIST OF TABLES

Table 1: Summary of Areas of Potential Environmental Concern	2
Table 2: City Directory Listings	7
Table 3: Summary of Aerial Photographs	10
Table 4: Current and Past Uses of the Phase One Property	19
Table 5: Summary of Areas of Potential Environmental Concern	20

LIST OF APPENDICES

Appendix A. Figures
Appendix B. Fire Insurance Plans
Appendix C. City Directories
Appendix D. ERIS Records
Appendix E. Regulatory Records and Requests
Appendix F. Aerial Photographs
Appendix G. Site Photographs



1. EXECUTIVE SUMMARY

Morrison Hershfield Limited (MH) was retained by The Regional Municipality of York (York Region) to conduct a Phase One Environmental Site Assessment (Phase One ESA) for a small portion of the property with municipal address of 10500 Dufferin Street in Vaughan, Ontario (herein referred to as the “Phase One Property”). The entire property is referred to as “Subject Property” for the purpose of this Phase One ESA. The Phase One ESA was conducted in support of the environmental assessment and preliminary design for road construction at Teston Road between Keele Street and Dufferin Street in Vaughan, Ontario (the Project).

This Phase One ESA was prepared in general accordance with Ontario Regulation (“O. Reg.”) 153/04 (as amended) to assess current and historic potentially contaminating activities (“PCAs”) that have occurred on the Phase One Property and on the surrounding properties within the 250 m radius (Phase One Study Area) that would contribute to an area of potential environmental concern (‘APEC’) on the Phase One Property. Morrison Hershfield understands that York Region is completing these due diligence activities in association with potential acquisition of the Phase One Property as part of the Project. With the addition of some key information, that would become available at later stages in the Project, this Phase One ESA may be suitable to be used in support of a filing of Record of Site Condition (RSC).

The Phase One Property is a rectangular shaped of land covering approximately an area of 1,000 square meters (m²). The Phase One Property is a small portion along the northern boundary of the Subject Property. Currently, the Phase One Property is residential land with landscape areas and asphalt driveway on-site. According to York Region Official Plan, Map 1A – Land Use Designation (July 2022), the Phase One Property is zoned as Community Area. The surrounding land use is a mix of undeveloped, residential and commercial properties. A general location map is provided as **Figure 1** and a site plan is included as **Figure 2** in **Appendix A**.

The site history and records review were principally informed by aerial photographs, former environmental reports, records from environmental databases (ERIS), and site reconnaissance. The review of the aerial photographs indicated that the Phase One Property was first developed as a landscape area and asphalt driveway for the residential dwellings at the Subject Property by 1964. The buildings on the Phase One Property were demolished in late 1990s and then the property remained a vacant land till 2010. The Phase One Property was re-developed as a landscape area and asphalt driveway for the residential building at the Subject Property in 2011.

Based on the findings of this Phase One ESA, one area of potential environmental concern was identified at the Phase One Property, due to historical fuel spills/leaks within the Phase One Study Area. The APEC is summarized in the **Table 1** below:

Table 1: Summary of Areas of Potential Environmental Concern

Area of Potential Environmental Concern (APEC)	Location of Area of Potential Environmental Concern on Phase One Property	Potential Contaminating Activity (PCA)	Location of PCA (On-Site or Off-Site)	Contaminants of Potential Concern	Media Potentially Impacted
APEC 1	Entire Phase One Property	<p>PCA#NA: Diesel fuel spill</p> <p>PCA#NA: Fuel oil spill/leak</p>	Off-site; adjacent east and adjacent south of the Phase One Property	PHCs, PAHs	Soil, Groundwater*

Notes:

**Groundwater will not be considered as potentially impacted medium unless impact is identified in soil.*

VOCs – Volatile Organic Compounds; PHC – Petroleum Hydrocarbon; PAHs – Polycyclic Aromatic Hydrocarbons, PCBs – Polychlorinated Biphenyls.

The evaluation of the Phase One Property concludes that there is a possibility that one or more contaminants of potential concern sourced from an off-site PCA within the Phase One Study Area, have affected soil or groundwater on, in, or under the Phase One Property. Therefore, a Phase Two ESA is required before an RSC can be submitted for the Phase One Property.

2. INTRODUCTION

Morrison Hershfield Limited (MH) was retained by for The Regional Municipality of York (York Region) to conduct a Phase One Environmental Site Assessment (Phase One ESA) for a small portion of the property with the municipal address of 10500 Dufferin Street in Vaughan, Ontario (herein referred to as the “Phase One Property”). The entire property is referred to as “Subject Property” for the purpose of this Phase One ESA. The Phase One ESA was conducted in support of the environmental assessment and preliminary design for road construction at Teston Road between Keele Street and Dufferin Street in Vaughan, Ontario (the Project).

This Phase One ESA was prepared in general accordance with Ontario Regulation (“O. Reg.”) 153/04 (as amended) to assess current and historic potentially contaminating activities (“PCAs”) that have occurred on the Phase One Property and on the surrounding properties within the 250 m radius (Phase One Study Area) that would contribute to an area of potential environmental concern (‘APEC’) on the Phase One Property. Morrison Hershfield understands that York Region is completing these due diligence activities in association with potential acquisition of the Phase One Property as part of the Project. With the addition of some key information, that would become available at later stages in the Project, this Phase One ESA may be suitable to be used in support of a filing of Record of Site Condition (RSC).

2.1 Phase One Property Information

The Phase One Property is a rectangular shaped land covering approximately an area of 1,000 square meters (m²). The Phase One Property is a small portion along the northern boundary of the Subject Property. Currently, the Phase One Property is residential land with landscape areas and asphalt driveway on-site. The building on the Subject Property is a multi-tenant residential building for retired seniors.

According to York Region Official Plan, Map 1A – Land Use Designation (July 2022), the Phase One Property is zoned as Community Area. Based on York Region Official Plan – Section 2.1.3, Community Area refers to land where residential, population-related employment and community services are directed to accommodate concentrations of existing and future population and employment growth. The surrounding land use is a mix of undeveloped, residential and commercial properties.

A general location map is provided as **Figure 1** and a site plan is included as **Figure 2** in **Appendix A**. The selected photographs of the Phase One Property are included in **Appendix G**.

3. SCOPE OF INVESTIGATION

The purpose of this Phase One ESA was conducted to determine the likelihood that contaminants have affected land or water on, in or under the Phase One property, and to determine the need for a Phase Two ESA.

The Phase One ESA was conducted following the principles of Ontario Regulation 153/04 Records of Site Condition, Part XV.1 of the Environmental Protection Act (EPA), as amended (O. Reg.153/04), and in accordance with generally accepted professional practices.

The scope of work of the Phase One ESA consisted of the following major activities:

- Reviewing the historical occupancy of the Phase One Property through the use of available archived and relevant municipal and business directories, topographical maps and aerial photographs.
- Contacting municipal and provincial agencies to determine the existence of records of environmental regulatory non-compliance, if any, and reviewing such records where available.
- Obtaining an Environmental Risk Information Services Ltd. (ERIS) report for the Phase One Property and surrounding properties within a 250 metre (m) radius of the Phase One Property.
- Reviewing available geological maps, well records and utility maps for the vicinity of the Phase One Property.
- Conducting a reconnaissance of the Phase One Property and surrounding properties, within a 250 metre (m) radius of the Phase One Property, to identify the presence of actual and/or potential environmental contaminants or environmental concerns of significance. Properties other than the Phase One Property were observed during a walk-by inspection from publicly accessible locations.
- Reviewing of previous environmental reports.
- Reviewing the current use of the Phase One Property and any land use practices that may have impacted its environmental condition.
- Reviewing the current use of the surrounding properties and any land use practices that may have impacted the environmental condition of the Phase One Property.
- Preparing a report to document the findings.

The Phase One ESA generally complies with O. Reg.153/04, with the following exceptions:

- A search of land title and assessment rolls for the Phase One Property was not conducted.
- A survey of the Phase One property was not completed.
- Interviews with designated site representative(s) as a resource for current and historical Phase One Property information was not conducted.

With the addition of this information, that would become available at later stages in the Project, this Phase One ESA may be suitable to support the filing of a Record of Site Condition (RSC) under Part XV.1 of the Environmental Protection Act.

In completing the scope of work, MH did not conduct any intrusive investigations, including sampling, analyses or monitoring. MH has confirmed neither the completeness nor the accuracy of any of the records that were obtained or any of the statements made by others. It is a basic assumption that any correspondence, material, data, evaluations, and reports furnished by others are free of latent deficiencies or inaccuracies.

4. RECORDS REVIEW

4.1 General

4.1.1 Phase One Study Area

The Phase One Study Area comprises the Phase One Property and surrounding properties wholly or partly within 250 meters (m) of the property boundaries as shown on **Figure 3** in **Appendix A**. The 250 m radius was used to gain an understanding of the current and past uses of surrounding properties to determine whether such uses may have contributed to subsurface environmental impacts at the Phase One Property.

Based on York Region Official Plan, the surrounding properties are zoned as Community Area, and/or Rural Area, characterized by residential and commercial properties, and undeveloped land.

4.1.2 First Developed Use

Aerial photographs dating back to 1959 and historical records were used to determine the approximate date and land use of first development. Based on the aerial photographs and historical records, the Phase One Property was first developed as a landscape area and asphalt driveway for the residential dwellings at the Subject Property by 1964.

Based on the limited information available, the first developed use of the Phase One Property is assumed to be in early 1960s.

4.1.3 Fire Insurance Plans

A search of available Fire Insurance maps and documents for the Phase One Property and the Phase One Study Area was requested to be conducted by Enviroscan through Opta Information Intelligence.

No fire insurance records were found for the Phase One Property or the Phase One Study Area. A copy of the search result is provided in **Appendix B**.

4.1.4 City Directories

As part of the historical searches for the occupancy of the Phase One Property and the surrounding properties, information from the City Directories information from the first available City Directory in 1960 to the most recently available, 2001 (at an approximate 5-year interval) was obtained for the Phase One Property plus surrounding properties from ERIS, and provided in **Appendix C**.

The city directory records indicate that there are no listings for Dufferin Street in the reviewed city directories from 1960 to 1970. In addition, the Subject Property (10500 Dufferin Street) was not listed in any of the city directories from 1960 to 2001.

The surrounding street, Teston Road, was also reviewed. In general, no occupants were listed for Teston Road in the reviewed city directories from 1960 to 1985. The commercial and industrial occupants within 250 m radius of the Phase One Property are summarized in **Table 1** below:

Table 2: City Directory Listings

Address	Listing	Years Listed
Dufferin Street		
10520	Honeypot Ranch, Automotive Video Productions	1985, 2001
10728	The Cottage Book	1995
10748	Blue Diamond	1990
10780	Stehower Landscape Contractor Designer, Stehower Landscape Centre Designer	1985, 1990
10790	Horizon House, Christian Horizons	1995, 2001
10800	De Melis S Construction	1985, 1990

No PCAs were identified based on the City Directories review alone.

4.1.5 Environmental Reports

Contamination Overview Study - Teston Road Area Transportation Improvements Individual Environmental Assessment, Morrison Hershfield, September 2, 2022.

A Contamination Overview Study (COS) report completed by MH in August 2020 was reviewed as part of this Phase One ESA. The COS was prepared to support the environmental assessment and preliminary design for road construction at Teston Road between Keele Street and Dufferin Street in Vaughan, Ontario. The COS included a records review of the Phase One Property and properties within 250 m of the Phase One Property, and a site reconnaissance by MH staff. The COS also included additional properties that were not part of this Phase One ESA. Based on the findings of the COS, no PCAs were identified for the Phase One Study Area.

4.2 Environmental Source Information

4.2.1 Environmental Databases

A standard search of provincial, federal and private databases for records pertaining to the Phase One Property and the surrounding properties within a 250 m radius was

completed by Environmental Risk Information Service (ERIS), an environmental database and information services company. A copy of the ERIS report is available in **Appendix D**, which also includes a description of each of the database sources.

ERIS reports provide environmental and historical information compiled from government and private source records. The report includes a search of over 60 databases for the Phase One Property and other properties within 250 m of the centre of the property. MH reviewed the information gathered from environmental databases compiled by ERIS to evaluate whether activities within the Phase One Study Area have the potential to impact the Phase One Property. It should be noted that this information is reported as MH received it from ERIS, which in turn reports information as it is provided in various databases. It is not possible for MH and / or ERIS to verify the accuracy or completeness of information contained in these databases. However, the use of and reliance on this information is generally an accepted practice in the conduct of environmental due diligence.

There are records in the ERIS report for Subject Property, however, there were no indications that the records are specifically for the Phase One Property. On this basis, all the records for the Subject Property are treated as off-site records.

There were 32 records identified for the properties within the 250 m Phase One Study Area. Off-site listings were identified in 5 databases in ERIS report. Those that are considered relevant to this investigation are summarized below:

Fuel Oil Spills and Leaks (INC)

The INC database has 1 record of spills for the Subject Property. The detail of the record is summarized below:

- A record for a spill/leak as a result of an incident with fuel storage at Subject Property. The record does not have any details regarding the quantity or type of fuel spill/leak. The record has the potential to impact the soil and/or groundwater quality at the Phase One Property.

Ontario Regulation 347 Waste Generators (GEN)

Entries in the GEN are for facilities that have registered as generators of subject waste, which included liquid industrial waste and hazardous waste. A total of 13 records from the Ontario Regulation 347 Waste Generators Summary database were found within 250 m of the Phase One Property, including:

- 7 listings for the Subject Property, registered under Richview Manor Vaughan Limited Partnership, for oil skimmings and sludges in 2013 to 2020.
- 2 listings for the property located at 1901 Teston Road, registered under Arborea Wood Products Inc., for waste oil and lubricants in 1997 to 1999.

- 4 listings for the property located at 10800 Dufferin Street, registered under City of Vaughan, for waste oil and sludges in 2018 to 2022.

The GEN records for properties generating subject wastes are consistent with the commercial nature of the surrounding area; however, there is no data to indicate that there were releases from any of these properties that would impact the Phase One Property.

Environmental Compliance Approvals (ECA)

Entries in the Environmental Compliance Approvals (ECA) are facilities that obtained approval for air, water, or waste management activities. The summary of the records is briefly described below:

- 2 records in ECA for the property located at 10820 Dufferin Street, registered under Nulook Developments Inc. for municipal and private sewage works.

Ontario Spills (SPL)

The SPL database has 1 record of spills within the Phase One Study Area. The detail of the record is summarized below:

- A record for a spill of 100 L of diesel fuel from a transport truck due to an accident at the intersection of Dufferin Street and Teston Road, approximately adjacent east of the Phase One Property. The spill record has the potential to impact the soil and/or groundwater quality at the Phase One Property.

Water Well Information System (WWIS)

A total of 15 records in the WWIS database were found for the Phase One Study Area, including:

- 5 domestic water supply wells, installed in 1955 and 1983.
- 4 abandoned wells, abandoned in between 1997 to 2018.
- 6 observation wells/monitoring wells, installed in between 1983 and 2018.

4.2.2 Municipal Records

A request to the York Region through the Freedom of Information (FOI) and Privacy Protection office for a search of their records associated with the Phase One Property was not initiated by MH as part of this Phase One ESA.

4.2.3 Ontario Ministry of the Environment, Conservation and Parks Documentation

Records pertaining to the Phase One Property were requested from the Ministry of the Environment, Conservation and Parks (MECP) on April 5, 2023. A response from MECP was received on May 5, 2023, indicating a record of Hazardous Waste Information Network (HWIN) number registered under Richview Manor Vaughan Limited Partnership for the waste class 251-L (Waste oils/sludges) generated at the Phase One Property. There is no data to indicate that there were releases from the Phase One Property that would impact soil and/or groundwater conditions at the Phase One Property. A copy of the FOI request and its response is included in **Appendix E**.

4.2.4 Technical Standards & Safety Authority

A request for information pertaining to the Phase One Property was made to the Technical Standards and Safety Authority (TSSA) on April 5, 2023. A response was received on April 6, 2023. No records were identified pertaining to the Phase One Property. A copy of the TSSA request, and the response is included in **Appendix E**.

4.3 Physical Setting Sources

4.3.1 Aerial Photographs

Aerial Photographs for the Phase One Study Area dated 1956, 1964, and 1973 were obtained from the City of Toronto online library and 1988 was obtained from York Region website. In addition, aerial photographs for the Phase One Study Area dated 1985, 2002, 2016, and 2022 were obtained from Google Maps satellite view. Aerial photographs were obtained from the earliest date available and at a reasonable frequency to capture significant changes that occurred on the subject property.

The aerial photographs were reviewed to determine the land uses at the Phase One Property and the surrounding properties within a 250 m radius, to identify areas of potential environmental concern. **Table 3** provides a summary of the review of aerial photographs and satellite imagery. Annotated versions of the photographs viewed are included in **Appendix F**.

Table 3: Summary of Aerial Photographs

Year	Phase One Property	Surrounding Properties
1956	The Phase One Property appears to be agricultural land.	North: A gravel road is noted north of the Phase One Property, followed by agricultural land. Residential property is noted at 175 m northwest of the Phase One Property.

Year	Phase One Property	Surrounding Properties
		<p>East: A developed road (currently known as Dufferin Street) is adjacent east of the Phase One Property, followed by agricultural land.</p> <p>South: Subject Property extends off-site towards the south. The area south of the Phase One Property appears to be agricultural, followed by undeveloped land.</p> <p>West: The area west of the Phase One Property appears to be agricultural, followed by undeveloped land.</p>
1964	The Phase One Property appears to be developed with landscape areas and asphalt driveways.	<p>North: No significant changes noted from the previous aerial photograph.</p> <p>East: No significant changes noted from the previous aerial photograph.</p> <p>South: The area adjacent south of the Phase One Property appears to be developed with residential dwellings.</p> <p>West: No significant changes noted from the previous aerial photograph.</p>
1973	No significant changes noted from the previous aerial photograph.	<p>North: Residential properties are developed 100 m north of the Phase One Property.</p> <p>East: No significant changes noted from the previous aerial photograph.</p> <p>South: No significant changes noted from the previous aerial photograph.</p> <p>West: No significant changes noted from the previous aerial photograph.</p>
1988	No significant changes noted from the previous aerial photograph.	<p>North: Further development of residential properties north of the Phase One Property.</p> <p>East: No significant changes noted from the previous aerial photograph.</p> <p>South: No significant changes noted from the previous aerial photograph.</p> <p>West: No other significant changes noted from the previous aerial photograph.</p>
2002	The Phase One Property appears to be vacant with overgrown vegetation and trees.	<p>North: No significant changes noted from the previous aerial photograph.</p> <p>East: No significant changes noted from the previous aerial photograph.</p> <p>South: The residential dwellings south of the Phase one Property are demolished. The area appears to be vacant with overgrown vegetation and trees.</p> <p>West: No significant changes noted from the previous aerial photograph.</p>

Year	Phase One Property	Surrounding Properties
2016	The Phase One Property appears to be re-developed with landscape areas and asphalt driveways.	<p>North: A commercial building (probably a fire station) is noted to be developed 100 m north of the Phase One Property.</p> <p>East: No significant changes noted from the previous aerial photograph.</p> <p>South: The area adjacent south of the Phase One Property appears to be developed with residential building.</p> <p>West: No significant changes noted from the previous aerial photograph.</p>
2022	The Phase One Property appears similar to the current configuration.	<p>North: Soil disturbance is noted at the property 50 m northwest of the Phase One Property.</p> <p>East: No other significant changes noted from the previous aerial photograph.</p> <p>South: No other significant changes noted from the previous aerial photograph.</p> <p>West: No significant changes noted from the previous aerial photograph.</p>

4.3.2 Topography, Hydrology and Geology

The Phase One Property is located within the Oak Ridges Moraines physiographic region (Chapman and Putnam, 1984). Based on available surficial geology maps, the underlying geology of the Phase One Property is sand and gravel, minor silt, clay and till. According to quaternary geology maps, the Phase One Property is within Halton Till with predominantly silt to silty clay. The bedrock consists of shale, limestone, dolostone, siltstone of Georgina Bay Formation; Blue Mountain Formation Billings Formation; Collingwood Member and Eastview Member (OGS, 2010).

The Phase One Property is at an elevation of approximately 265 metres above sea level (mASL) (Toporama). The elevation of the Phase One Study Area to the east of the Phase One Property is 275 mASL and Phase One Study Area to the west drops to 253 mASL at the nearest surface water body. The nearest waterbody is a tributary of Don River East Branch running from northwest to southwest of the Phase One Property, located approximately 200 m west of the Phase One Property. Based on topographic maps, the direction of regional groundwater flow is to the west towards Don River East Branch. However, underground features such as utility corridors may locally influence groundwater flow. The actual groundwater flow direction and depth at the Phase One Property cannot be determined without site-specific groundwater monitoring well data. **Figure 3** presents the topographic details.

The surface of the Phase One Property is covered with surficial soil, vegetation and asphalt driveways. Stormwater generated at the Phase One Property will either infiltrate the ground surface or flow overland towards the catch basins on Teston Road/Dufferin Street for eventual discharge into the municipal storm sewers.

4.3.3 Fill Materials

No evidence of importation of fill materials of unknown origin at the Phase One Property has been identified.

4.3.4 Water Bodies and Areas of Natural Significance

Based on the Ministry of Natural Resources web mapping tool, there is an area of natural and scientific interest (ANSI) located 60 m west, a natural heritage system located 60 m west and 10 m east, and a provincially significant wetland and a surface water body located 160 m west of the Phase One Property.

Based on the Ministry of Natural Resources web mapping tool, an area designated as Settlement Area Land Use, described under the Oak Ridges Moraine Conservation Plan is located at the Phase One Property. In addition, an area designated as Natural Core Area Land Use, described under the Oak Ridges Moraine Conservation Plan is located 50 m west and 10 m east of the Phase One Property.

On the basis of the discussion provided above, the Phase One Property is an environmentally sensitive area with respect to areas of natural significance.

4.3.5 Well Records

A search of the MECP Water Well Information System (WWIS) database was conducted for all water wells within a 250 m radius of the Phase One Property. According to the WWIS, a total of 15 records from the Water Well Information System database were found within 250 m of the Phase One Property, including 5 domestic water supply wells, and 6 observation/monitoring wells. The water supply wells were installed in between 1955 and 1983, and the observation/ monitoring wells were installed in between 1997 and 2018.

The water supply wells within the Phase One Study Area were likely used before the development of the Phase One Study Area. During the development of the Phase One Study Area, the water supply wells were likely abandoned. Currently, the potable water is supplied by the York region within the Phase One Study Area.

The identified stratigraphy generally followed the expectation for the Phase One Study Area, with high permeability silty sand layer overlying a lower permeability silt/clay layer. The thickness of the silty sand layer varied considerably, extending from 2 m to 13 m. Bedrock was not encountered in any of these monitoring wells and static water level was reported in be in the range of 4 to 6 meters below ground surface (mbgs).

The WWIS locations are shown on **Figure 3 in Appendix A**. It should be noted that the margin of error for the location of these well records ranges from 100 to 300 metres.

4.3.6 Site Operating Records

No site operating records were available for review.

5. INTERVIEWS

No interview has been conducted as part of this Phase One ESA regarding the current and historical operations at the Phase One Property.

6. SITE RECONNAISSANCE

6.1 General Requirements

The purpose of the site reconnaissance is to document any areas of potential environmental concerns (APEC) and/or potential contaminating activities (PCA) which may be contributing to or causing a potential environmental concern, and to identify any structures or other significant Phase One Property features.

The site reconnaissance was conducted on September 8th, 2022, by Mr. Nicholas Moore and Mr. Sarth Sheth of MH, under the supervision of Ms. Chloe Zhang, M.A.Sc., P.Geo. (formerly of MH). The weather conditions were partly cloudy and approximately 20°C at the time of reconnaissance. MH staff performed a self-guided walkthrough of the Phase One Property and a self-guided review of the Phase One Study Area from publicly accessible vantage points. Annotated photographs taken during the site reconnaissance are provided in **Appendix G**.

6.2 Specific Observations at the Phase One Property

6.2.1 Layout, Tanks, Potable Water Sources

The Phase One Property is comprised of landscape areas and asphalt driveways. No evidence of historical storage tanks was noted at the Phase One Property. The potable water at the Phase One Property is supplied by the York Region.

6.2.2 Buildings and Structures

No building or structure is currently present at the Phase One Property.

6.2.3 Utilities

Water hydrants were noted at the Phase One Property. No other evidence of on-site utilities was observed at the Phase One Property.

During the site reconnaissance numerous overhead wires (including electrical wires), fire hydrants, catch basins and manholes were observed within the surrounding area.

6.2.4 Wells, Sewage Works, Ground Surface and Railway Lines

No groundwater wells (domestic or monitoring wells) were observed at the Site during the site reconnaissance. The ground surface of the Site is covered with surficial soil/grass, and shrubs. Sewage works were not observed to be present at the Site. Railway lines were not observed within the Phase One Study Area.

6.2.5 Land (Signs of Contamination)

The Phase One Property was inspected for areas of stained soil, vegetation or pavement; areas of stressed vegetation; areas of placed fill or debris; potentially contaminating activities; and unidentified substances. No stained soil, signs of dumping, fill, or stressed vegetation was observed.

6.2.6 Special Attention Substances

MH reviewed the Phase One Property for the potential presence of “special attention” items during the site visit. The special substances are regulated through federal or provincial regulations and may represent a health concern if there is exposure, and/or require proper handling, storage, and disposal. These special attention items include Polychlorinated Biphenyls (PCBs), ozone-depleting materials (ODMs), urea foam formaldehyde insulation (UFFI), asbestos, radon, mould, noise and vibrations, and electric/magnetic fields (EMF).

No evidence of potential sources for PCBs, ODMs, UFFI, asbestos, radon, mould, noise and vibrations, and EMF were identified at the Phase One Property during the site reconnaissance.

6.3 Enhanced Investigation Property

The Phase One Property is not and has never been a garage, fuelling facility or dry-cleaning facility. The Phase One Property does not meet the criteria for an enhanced investigation property as defined by clause 32 (1) (b) of the O. Reg 153/04.

6.4 Observations Within the Phase One Study Area

The surrounding properties in the immediate vicinity of the Phase One Property were also inspected during the site reconnaissance. Generally, properties surrounding the Phase One Property to the north and south are residential, whereas the properties to the east and west of the Phase One Property are undeveloped.

North: Adjacent to the Phase One Property to the north is Teston Road, followed by residential properties and a fire station.

East: The Phase One Property is bound to the east by Dufferin Street, followed undeveloped land.

South: The Phase One Property is bound to the south by a residential property, followed undeveloped land.

West: The Phase One Property is bound to the west by an undeveloped land.

6.5 Written Description of Investigation

Section 15 of the O. Reg. 153/04 requires a written description of the investigations conducted on the Phase One Property and in the Phase One Study Area, including any findings that are relevant to the existence of an APEC. This requirement is addressed in the relevant sections of this report.

7. REVIEW AND EVALUATION OF INFORMATION

7.1 Current and Past Uses of Phase One Property

The Phase One Property is a small portion of the property with the municipal address of 10500 Dufferin Street in Vaughan, Ontario. Aerial photographs dating back to 1959 were used to determine the approximate date and land use of first development. The Phase One Property was developed as a landscape area and asphalt driveway for the residential dwellings at the Subject Property by 1964. The Phase One Property buildings were demolished in late 1990s and then remained vacant land till 2010. The Phase One Property was re-developed as a landscape area and asphalt driveway for the residential building at the Subject Property in 2011. No changes to the Phase One Property occurred since 2011.

Current and past uses of the Phase One Property, as identified from the Phase One ESA are summarized in Table 4.

Table 4: Current and Past Uses of the Phase One Property

Year	Name of Owner ²	Description of Property Use	Property Use ¹	Other Observations from Aerial Photographs, Fire Insurance Plans, etc.
Up to approximately 1960s	Not available	Agricultural	Agriculture or other use	– 1959 aerial photograph indicated agricultural land.
1964 -1999	Not available	Landscape area and asphalt driveway for the residential dwellings at the Subject Property	Residential use	– 1964 to 1988 aerial photographs indicated landscape area and asphalt driveway at the Phase One Property.
Late 1990s - 2010	Not available	Vacant land	Agriculture or other use	– 2002 aerial photograph indicated that the residential dwellings at the Subject property has been demolished. Phase One Property appears to be a vacant land.
2011 - Present	Not available	Landscape area and asphalt driveway for the residential dwellings at the Subject Property	Residential use	– 2016 and 2022 aerial photographs indicated landscape area and asphalt driveway at the Phase One Property.

Notes:

1 - for each owner, specify one of the following types of property use (as defined in O. Reg. 153/04) that applies:

Agriculture or other use; Commercial use; Community use; Industrial use; Institutional use; Parkland use; Residential use

2 - Please note, this table cannot be completed to the standard of O. Reg. 153/04 until ownership of the property parcel(s) is confirmed, and chain of title obtained.

7.2 Potentially Contaminating Activity

Per O. Reg. 153/04, Potentially Contaminating Activity (PCA), means “a use or activity set out in Column A or Table 2 of Schedule D that is occurring or has occurred in a Phase One Study Area”. The PCAs identified at the Phase One Property and within the Phase One Study Area are described in the sections below.

7.2.1 Phase One Property

No PCAs were identified for the Phase One Property.

7.2.2 Phase One Study Area

The following PCAs were identified within the study area:

- **PCA# Not Available (NA)**, based on the spill of 100 L of diesel fuel from a transport truck due to an accident at the intersection of Dufferin Street and Teston Road, adjacent east of the Phase One Property.
- **PCA# Not Available (NA)**, based on the fuel oil spill/leak record for the Subject Property.

7.3 Areas of Potential Environmental Concern

Based on the findings from records review, and site reconnaissance, one area of potential environmental concern (APEC) was identified on the Phase One Property associated with two off-site PCAs, as summarized in **Table 5**. The locations of the PCAs and APEC are provided on **Figure 4**.

Table 5: Summary of Areas of Potential Environmental Concern

Area of Potential Environmental Concern (APEC)	Location of Area of Potential Environmental Concern on Phase One Property	Potential Contaminating Activity (PCA)	Location of PCA (On-Site or Off-Site)	Contaminants of Potential Concern	Media Potentially Impacted
APEC 1	Eastern portion of the Phase One Property	PCA#NA: Diesel fuel spill PCA#NA: Fuel oil spill/leak	Off-site; adjacent east and adjacent south of the Phase One Property	PHCs, PAHs	Soil, Groundwater*

Notes:

**Groundwater will not be considered as potentially impacted medium unless impact is identified in soil.
VOCs – Volatile Organic Compounds; PHC – Petroleum Hydrocarbon; PAHs – Polycyclic Aromatic Hydrocarbons, PCBs – Polychlorinated Biphenyls.*

7.4 Phase One Conceptual Site Model

The Phase One Conceptual Site Model (CSM) was compiled from the information provided in **Table 5** and information shown on **Figure 1** through **Figure 4**. A site location plan providing the names of roadways within the Phase One Study Area and showing adjacent properties is provided as **Figure 3**.

No evidence of utilities at the Phase One Property was observed during the site reconnaissance. No water supply wells were located at the Site. The Site and the area in the vicinity of the Site are municipally serviced and the groundwater is not considered as a potable water source.

Based on the Ministry of Natural Resources web mapping tool, an area designated as Settlement Area Land Use, described under the Oak Ridges Moraine Conservation Plan is located at the Phase One Property. In addition, an area designated as Natural Core Area Land Use, described under the Oak Ridges Moraine Conservation Plan is located 50 m west and 10 m east of the Phase One Property. On this basis, the Phase One Property is an environmentally sensitive area with respect to areas of natural significance.

Areas where PCAs are potentially affecting the Phase One Property and associated contaminants of potential concern are provided on **Table 5** in **Section 7.3** of this report. Only one area of potential environmental concern (APEC) was identified on the Phase One Property associated with two off-site PCAs.

Based on topographic maps, the regional groundwater flow is to the west towards the Don River West Branch. However, underground features such as utility corridors may locally influence groundwater flow within the Phase One Study Area. The actual groundwater flow direction and depth at the Phase One Property cannot be determined without site-specific groundwater monitoring well data.

The Phase One Property is located within the Oak Ridges Moraines physiographic region (Chapman and Putnam, 1984). Based on available surficial geology maps, the underlying geology of the Phase One Property is sand and gravel, minor silt, clay and till. According to quaternary geology maps, the Phase One Property is within Halton Till with predominantly silt to silty clay. The bedrock consists of shale, limestone, dolostone, siltstone of Georgina Bay Formation; Blue Mountain Formation Billings Formation; Collingwood Member and Eastview Member. (OGS, 2010).

The identified stratigraphy generally followed the expectation for the Phase One Study Area, with high permeability silty sand layer overlying a lower permeability silt/clay layer.

The thickness of the silty sand layer varied considerably, extending from 2 m to 13 m. Bedrock was not encountered in any of these monitoring wells and static water levels was reported in be in the range of 4 to 6 meters below ground surface (mbgs).

The QP has determined that there isn't any uncertainty or absence of information obtained for any of the components of the Phase One ESA that would affect the validity of the Phase One CSM.

8. CONCLUSIONS

Based on the findings of this Phase One ESA, one area of potential environmental concern was identified at the Phase One Property, due to historical fuel spills/leaks within the Phase One Study Area.

8.1 Whether a Phase Two ESA is Required Before Record of Site Condition Submitted

Based on the logic and reasoning provided in the preceding sections of this report, the evaluation of the Phase One Property concludes that there is a possibility that one or more contaminants of potential concern either sourced from the Phase One Property, or from an off-site PCA within the Phase One Study Area, have affected soil or groundwater on, in, or under the Phase One Property. Therefore, a Phase Two ESA is required before an RSC can be submitted for the Site.

8.2 Record of Site Condition Based on Phase One Environmental Site Assessment Alone

An RSC will not be filed based on the findings of this Phase One ESA alone.

8.3 Qualifications of Assessors

Ali Sultan, M.Sc., EIT - The document review and report preparation were conducted by Mr. Ali Sultan, in MH's Markham, Ontario office. Mr. Sultan has been involved in site visits, interviews, historical research, groundwater, and soil sampling, drilling, excavations, pump-and-treat maintenance, test pitting, air photo identification and report writing for Phase I & II ESAs across Ontario in commercial and industrial sectors under CSA Z768-01, CSA Z769-00, Ontario Regulation 153/04 and ASTM standards. Mr. Sultan is an Environmental Engineering In Training under Professional Engineers Ontario (PEO). Mr. Sultan holds an Undergraduate degree in Chemical Engineering, and a Post Graduate Certificate in Environmental Engineering Applications, and has over four years of professional experience.

Anthony (Ant) West, Ph.D., P.Eng., QP_{ESA} - The Phase One ESA was performed under the overall direction of Dr. Anthony (Ant) West. Dr. West is a Senior Environmental Engineer, manager of our environmental engineering and geoscience team, and our company's key contact for hydrogeology, contaminants, and hazardous materials. Ant has been working in contaminated sites assessment and remediation, hazardous materials assessment and abatement, and contaminant and physical hydrogeology for close to thirty years, including during his graduate studies from 1998 to 2006. Dr. West meets the requirements to act as a Qualified Person, other than risk assessment, under O. Reg. 153/04.

8.4 Signatures

The findings and conclusion of this report have been supervised by the undersigned Qualified Person (QP). As a QP ESA, I confirm that I have supervised the carrying out of the Phase One ESA, the findings and the conclusions of this report.

We trust the information presented in this report meets your requirements. If you should have any further questions or need additional details, please do not hesitate to contact our office.

Morrison Hershfield Limited

Phase One Written By:



Ali Sultan, M.Sc., EIT.
Environmental Engineer In Training
asultan@morrisonhershfield.com
416 499 3110 Ext. 1011109

Phase One Supervised By:



Anthony (Ant) West, Ph.D., P.Eng., QP_{ESA}
Manager, Environmental Engineering and
Geoscience, East
awest@morrisonhershfield.com
613 739 2910 Ext. 1022424

9. LIMITATIONS AND USE OF REPORT

This report has been prepared for the exclusive use of The Regional Municipality of York (the Client) by Morrison Hershfield Limited (Morrison Hershfield). Morrison Hershfield hereby disclaims any liability or responsibility to any person or party, other than the Client, for any loss, damage, expense, fines, or penalties which may arise from the use of any information or recommendations contained in this report.

In preparing this report Morrison Hershfield has relied in good faith on information provided by individuals and companies noted in this report. Morrison Hershfield assumes that the information provided is factual and accurate, and accepts no responsibility for any deficiency, misstatements or inaccuracies contained in this report as a result of omissions, misinterpretations or fraudulent acts of the persons interviewed or contacted.

The report, which specifically includes all tables, figures and appendices is based on data and information collected during investigations conducted by Morrison Hershfield and is based solely on the conditions of the site at the time of the investigation, supplemented by historical information and data obtained by Morrison Hershfield as described in this report. Limitations of the data and information include the fact that conditions between and beyond the limited number of sampling locations may vary; that the assessment is dependent upon the accuracy of the analytical data generated through sample analysis; and that contaminants may exist for which no analyses have been conducted. Furthermore, no assurance is made regarding changes in conditions and/or the regulatory regime (standards, guidelines, etc.), subsequent to the time of investigation.

Morrison Hershfield has exercised professional judgment in collecting and analyzing the information and formulating recommendations based on the results of the study. The services performed as described in this report were conducted in a manner consistent with that level of care and skill normally exercised by other members of the engineering and science professions currently practicing under similar conditions, subject to the time limits and financial and physical constraints applicable to this study. No other warranty or representation, either expressed or implied, as to the accuracy of the information or recommendations included or intended in this report.

10. REFERENCES

Chapman, L.J. and Putnam, D.F., 1984.

The Physiography of Southern Ontario, Ontario Geological Survey, Special Volume 2. Ontario.

City of Toronto:

Toronto Aerial Photos Library website (<https://www.toronto.ca/city-government/accountability-operations-customer-service/access-city-information-or-records/city-of-toronto-archives/whatsonline/maps/aerial-photographs/>, accessed September 2020)

Environmental Risk Information Service (ERIS):

ERIS - 22090200348 – January 27, 2023

Geological Survey of Canada:

Quaternary Geology of Ontario. Scale 1:1,000,000. Map 2556. 1991.

Bedrock Geology of Ontario. Scale 1:1,000,000. Map 2544. 1991.

Morrison Hershfield Limited, 2020

Contamination Overview Study, Teston Road Area Transportation Improvements Individual Environmental Assessment, September 2, 2020.

Ontario Geological Survey, 2010:

Surficial geology of Southern Ontario; Ontario Geological Survey, Miscellaneous Release--Data 128-REV, accessed March 20, 2023.

Opta Historical Environmental Services Envirosan (Opta)


Opta 22091304525 – September 20, 2022

Toporama, The Atlas of Canada:

<https://atlas.gc.ca/toporama/en/index.html>, accessed March 20, 2023.

APPENDIX A: FIGURES






LEGEND

 Approximate Site Location

NOTES:
- MNRF Aurora District



Coordinate System: NAD 1983 UTM Zone 17N
Sources: MNRF



TITLE: **Site Location Map**

PROJECT NO.: 190261800
**Phase One ESA, Property 8
Teston Road, Vaughan Ontario**

DATE: **March 2023** **Figure 1**

Sources: Esri, HERE, Garmin, USGS, Intermap, INCREMENT P, NRCan, Esri Japan, METI, Esri China (Hong Kong), Esri Korea, Esri (Thailand), NGCC, (c) OpenStreetMap contributors, and the GIS User Community



LEGEND


- Site Boundaries
- Land Information Ontario Data**
- Watercourses
- Waterbodies
- Transportation Network**
- Arterial / Collector
- Local Roads

NOTES:

- MNRF Aurora District



Coordinate System: NAD 1983 UTM Zone 17N
Sources: MNRF




TITLE:
Site Layout

PROJECT NO.: 190261800
**Phase One ESA, Property 8
Teston Road, Vaughan Ontario**

DATE: **March 2023** **Figure 2**

Source: Esri, Maxar, Earthstar Geographics, and the GIS User Community




LEGEND

- Site Boundaries
- Phase One Study Area (250 m)
- Water Wells in Provincial System (WWIS)**
 - Domestic
 - Monitoring
 - Not Used
- Land Information Ontario Data**
 - Topographic Contour (mASL)
 - Watercourses
 - Waterbodies
 - ANSI
 - Wooded Areas
- Oak Ridge Moraine Conservation Plan**
 - Countryside Area
 - Settlement Area
 - Natural Core Area
 - Natural Linkage Area
- Wetland**
 - Evaluated-Provincially Significant Wetlands
- Transportation Network**
 - Arterial / Collector
 - Local Roads

NOTES:
- MNRF Aurora District




Coordinate System: NAD 1983 UTM Zone 17N
Sources: MNRF



TITLE:
Natural Features and Water Wells


PROJECT NO.: 190261800
**Phase One ESA, Property 8
Teston Road, Vaughan Ontario**

DATE: **March 2023** **Figure 3**




- LEGEND**
- Site Boundaries
 - Phase One Study Area (250 m)
 - APEC 1
- Potentially Contaminating Activities**
- * PCA#NA - Diesel Fuel Spill
 - * PCA#NA - Fuel Oil Spill/Leak
- Land Information Ontario Data**
- Watercourses
 - Waterbodies
- Transportation Network**
- Arterial / Collector
 - Local Roads

NOTES:
- MNRF Aurora District



Coordinate System: NAD 1983 UTM Zone 17N
Sources: MNRF



TITLE:
Areas of Potential Contamination Concern (APECs) and Potentially Contaminating Activities (PCAs)

PROJECT NO.: 190261800
**Phase One ESA, Property 8
Teston Road, Vaughan Ontario**

DATE: **April 2023** **Figure 4**

Area of Potential Environmental Concern (APEC)	Potential Contaminating Activity (PCA)	Location of PCA (On-site or Off-site)	Contaminants of Potential Concern	Media Potentially Impacted
APEC 1	PCA#NA: Diesel fuel spill PCA#NA: Fuel oil spill/leak	Off-site; adjacent east and south of the Phase One Property	PHCs, PAHs	Soil, Groundwater*

Source: Esri, Maxar, Earthstar Geographics, and the GIS User Community

APPENDIX B: FIRE INSURANCE PLANS





enviroscan



An SCM Company

175 Commerce Valley Drive W
Markham, Ontario L3T 7Z3

T: 905-882-6300
W: www.optaintel.ca

Report Completed By:

Swati

Site Address:

Teston Rd Vaughan ON Canada

Project No:

22090200347

Opta Order ID:


113922

Requested by:

Eleanor Goolab
ERIS

Date Completed:

9/12/2022 12:12:30 PM



Opta Historical Environmental Services EnviroscanTM Terms and Conditions

Report

The documents (hereinafter referred to as the "Documents") to be released as part of the report (hereinafter referred to as the "Report") to be delivered to the purchaser as set out above are documents in Opta's records relating to the described property (hereinafter referred to as the "Property"). Opta makes no representations or warranties respecting the Documents whatsoever, including, without limitation, with respect to the completeness, accuracy or usefulness of the Documents, and does not represent or warrant that these are the only plans and reports prepared in association with the Property or in Opta's possession at the time of Report delivery to the purchaser. The Documents are current as of the date(s) indicated on them. Interpretation of the Documents, if any, is by inference based upon the information which is apparent and obvious on the face of the Documents only. Opta does not represent, warrant or guarantee that interpretations other than those referred to do not exist from other sources. The Report will be prepared for use by the purchaser of the services as shown above hereof only.

Disclaimer

Opta disclaims responsibility for any losses or damages of any kind whatsoever, whether consequential or other, however caused, incurred or suffered, arising directly or indirectly as a result of the services (which services include, but are not limited to, the preparation of the Report provided hereunder), including but not limited to, any losses or damages arising directly or indirectly from any breach of contract, fundamental or otherwise, from reliance on Opta Reports or from any tortious acts or omissions of Opta's agents, employees or representatives.

Entire Agreement

The parties hereto acknowledge and agree to be bound by the terms and conditions hereof. The request form constitutes the entire agreement between the parties pertaining to the subject matter hereof and supersedes all prior and contemporaneous agreements, negotiations and discussions, whether oral or written, and there are no representations or warranties, or other agreements between the parties in connection with the subject matter hereof except as specifically set forth herein. No supplement, modification, waiver, or termination of the request shall be binding, unless confirmed in writing by the parties hereto.

Governing Document

In the event of any conflicts or inconsistencies between the provisions hereof and the Reports, the rights and obligations of the parties shall be deemed to be governed by the request form, which shall be the paramount document.

Law

This agreement shall be governed by and construed in accordance with the laws of the Province of Ontario and the laws of Canada applicable therein.

No Records Found

Requested by:
Eleanor Goolab

Date Completed: 09/12/2022 12:12:30



OPTA INFORMATION INTELLIGENCE

No Records Found



APPENDIX C: CITY DIRECTORIES



ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES



CITY
DIRECTORY

Project Property: *2270 Teston Road, Vaughan, Ontario*
Report Type: *City Directory*
Order No: *22090200349*
Information Source: *Polk York Region Ontario*
Date Completed: *Sep 20, 2022*

Environmental Risk Information Services

A division of Glacier Media Inc.

1.866.517.5204 | info@erisinfo.com | erisinfo.com

City Directory Information Source

Polk York Region Ontario

PROJECT NUMBER: 22090200349	
Site Address:	2270 Teston Road, Vaughan, Ontario
Year: 2001	
Site Listing:	-Residential (1 Tenant)
Adjacent Properties:	
Teston Road (2175-2430)	2175-Fabco Plastics Wholesale Ltd -Fabco Systems -Fabricated Plastics Ltd -Hytek Plastic Sales -Kemflo Canada Inc 2411 -Residential (1 Tenant) 2430 -Residential (2 Tenants)
D'Amato Crescent (All)	-All Residential
Isaac Murray Avenue (268-371)	291 -Residential (1 Tenant)
Keele Street (10695-10721)	10695-Macri Sand & Gravel

	-Parente Garage 10721-M&CC Ltd -Modular & Custom Cabinets Ltd -Modular Shelf Centre Ltd
--	--

PROJECT NUMBER: 22090200349	
Site Address:	2270 Teston Road, Vaughan, Ontario
Year: 1995	
Site Listing:	-Address Not Listed
Adjacent Properties:	
Teston Road (2175-2430)	2175-Fabco Plastics Wholesale Ltd -Fabco Systems -Fabricated Plastics Ltd -Hytek Plastic Sales 2381 -Residential (1 Tenant) 2411 -Residential (1 Tenant) 2430 -Residential (1 Tenant)
D'Amato Crescent (All)	-Street Not Listed
Isaac Murray Avenue (268-371)	-Street Not Listed

Keele Street (10695-10721)	10721-M&CC Ltd & Custom Cabinets Ltd -Modular & Custom Cabinets Ltd -Modular Shelf Centre Ltd

PROJECT NUMBER: 22090200349	
Site Address:	2270 Teston Road, Vaughan, Ontario
Year: 1990	
Site Listing:	-Residential (1 Tenant)
Adjacent Properties:	
Teston Road (2175-2430)	2175-Fabco Systems 2381 -Residential (1 Tenant) 2411 -Residential (1 Tenant) -Pisa Construction 2430 -Residential (1 Tenant) -Blue Crest Construction Ltd
D'Amato Crescent (All)	-Street Not Listed
Isaac Murray Avenue (268-371)	-Street Not Listed

Keele Street (10695-10721)	10721-Modular & Custom Cabinets Ltd -Modular Shelf Centre Ltd

PROJECT NUMBER: 22090200349	
Site Address:	2270 Teston Road, Vaughan, Ontario
Year: 1985	
Site Listing:	-Street Not Listed
Adjacent Properties:	
Teston Road (2175-2430)	-Street Not Listed
D'Amato Crescent (All)	-Street Not Listed
Isaac Murray Avenue (268-371)	-Street Not Listed
Keele Street (10695-10721)	10721-Modular & Custom Cabinets Ltd

PROJECT NUMBER: 22090200349	
Site Address:	2270 Teston Road, Vaughan, Ontario

Year: 1979	
Site Listing:	-Street Not Listed
Adjacent Properties:	
Teston Road (2175-2430)	-Street Not Listed
D'Amato Crescent (All)	-Street Not Listed
Isaac Murray Avenue (268-371)	-Street Not Listed
Keele Street (10695-10721)	-No Listings Within Radius

PROJECT NUMBER: 22090200349	
Site Address:	2270 Teston Road, Vaughan, Ontario
Year: 1975	
Site Listing:	-Street Not Listed
Adjacent Properties:	

Teston Road (2175-2430)	-Street Not Listed
D'Amato Crescent (All)	-Street Not Listed
Isaac Murray Avenue (268-371)	-Street Not Listed
Keele Street (10695-10721)	-No Listings Within Radius

PROJECT NUMBER: 22090200349	
Site Address:	2270 Teston Road, Vaughan, Ontario
Year: 1970/71	
Site Listing:	-Street Not Listed
Adjacent Properties:	
Teston Road (2175-2430)	-Street Not Listed
D'Amato Crescent (All)	-Street Not Listed
Isaac Murray Avenue (268-371)	-Street Not Listed
Keele Street (10695-10721)	-No Listings Within Radius

PROJECT NUMBER: 22090200349	
Site Address:	2270 Teston Road, Vaughan, Ontario
Year: 1966	
Site Listing:	-Street Not Listed
Adjacent Properties:	
Teston Road (2175-2430)	-Street Not Listed
D'Amato Crescent (All)	-Street Not Listed
Isaac Murray Avenue (268-371)	-Street Not Listed
Keele Street (10695-10721)	-Street Not Listed

PROJECT NUMBER: 22090200349	
Site Address:	2270 Teston Road, Vaughan, Ontario
Year: 1960	
Site Listing:	-Street Not Listed
Adjacent Properties:	

Teston Road (2175-2430)	-Street Not Listed
D'Amato Crescent (All)	-Street Not Listed
Isaac Murray Avenue (268-371)	-Street Not Listed
Keele Street (10695-10721)	-Street Not Listed

-All listings for businesses were listed as they are in the city directory.

-Listings that are residential are listed as "residential" with the number of tenants. The name of the residential tenant is not listed in the above city directory.

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES



CITY
DIRECTORY

Project Property: *Phase I ESA - Teston Rd, Vaughan, Ontario*
Report Type: *City Directory*
Order No: *22090200347*
Information Source: *Polk York Region Ontario*
Date Completed: *Sep 20, 2022*

Environmental Risk Information Services

A division of Glacier Media Inc.

1.866.517.5204 | info@erisinfo.com | erisinfo.com

City Directory Information Source

Polk York Region Ontario

PROJECT NUMBER: 22090200347	
Site Address:	Phase I ESA - Teston Rd, Vaughan, Ontario
Year: 2001	
Site Listing:	-No Site Civic Address Identified
Adjacent Properties:	
Teston Road (1500-2190)	1600 -Residential (1 Tenant) 2101-Connolly Marble & Granite -Cormil Drywall Inc -Global Precast -Stock Mechanical -World Waste System Corp 2175-Fabco Plastics Wholesale Ltd -Fabco Systems -Fabricated Plastics Ltd -Hytek Plastic Sales -Kemflo Canada Inc
Dufferin Street (10500-10800)	10520-Automotive Video Productions 10780 -Residential (2 Tenants)

	10790-Christian Horizons 10800 -Residential (1 Tenant)
Germana Place (56-101)	-Street Not Listed
84 Malmo Court	-A&T Auto Refinishing -Blakelock K H Disposal Services -Fiedler Technology Ltd -Iveco Equipment -NP Services -Peppo Foods Ltd -R&W Maintenance Ltd -Tagg Industries -Top Motors -Residential (1 Tenant)
Rodinea Road (21-99)	45-Alpha Elegant Metal & Paper International Inc -Amerco Rentals -EG Construction Fence Rental -J&M Auto Service -The Restorers Group Inc -Solid Wall Concrete Forming -TNT Metal Stripping Inc -UHaul Co Ltd -Wirecomm Systems Inc 67-Cedarcraft Woodworks

	<ul style="list-style-type: none"> -Cool Comfort Heating & Air Conditioning -Doors & More By DDR Ltd -Houston Marine Systems -June Acupuncture -Nortown Self Storage -Sartor & Susin -Residential (1 Tenant) 75-Automatic Compactors 99-Alsi Contracting Ltd -GBM Rivet & Fasteners Inc
--	---

PROJECT NUMBER: 22090200347	
Site Address:	Phase I ESA - Teston Rd, Vaughan, Ontario
Year: 1995	
Site Listing:	-No Site Civic Address Identified
Adjacent Properties:	
Teston Road (1500-2190)	<ul style="list-style-type: none"> 1600 -Residential (1 Tenant) 2101-Cormil Drywall Inc -Stock Mechanical -Topax Export Packing Systems 2175-Fabco Plastics Wholesale Ltd

	<ul style="list-style-type: none"> -Fabco Systems -Fabricated Plastics Ltd -Hytek Plastic Sales
Dufferin Street (10500-10800)	<ul style="list-style-type: none"> 10728-The Cottage Book 10748 -Residential (2 Tenants) 10780 -Residential (2 Tenants) 10790-Horizon House 10800 -Residential (1 Tenant)
Germana Place (56-101)	-Street Not Listed
84 Malmo Court	<ul style="list-style-type: none"> -Autograffs -Blakelock KH Disposal Services -Fiedler Technology Ltd -Iveco Equipment -Iveco Excavating -Marcello & Tony Auto Centre -Northern Distributors -Pedovani Guido Painting Contractors -Tagg Industries -Residential (1 Tenant)
Rodinea Road (21-99)	<ul style="list-style-type: none"> 21-Jager Industries Inc 45-Alpha Alex Metal Co Ltd -Amerco Rentals

	<ul style="list-style-type: none"> -Clearway Construction Inc -DCL Co Inc -Downsview Group -Gilbat Metals Ltd -J&M Auto Service -Silvio Constructions Co Ltd -Stahlike Excavating Ltd -Teston Pipeline -U Haul Co Ltd 67-Boston Mechanical Contractors Ltd -Cool Comfort Heating & Air Conditioning -Doors & More By DDR Ltd -Nucorp Products -Saritor & Susin 75-Automatic Compactors 99-Maple Stamping 2 -Richmond Wood Products Ltd
--	---

PROJECT NUMBER: 22090200347	
Site Address:	Phase I ESA - Teston Rd, Vaughan, Ontario
Year: 1990	
Site Listing:	-No Site Civic Address Identified

Adjacent Properties:	
Teston Road (1500-2190)	1600 -Residential (1 Tenant) 2175-Fabco Systems
Dufferin Street (10500-10800)	10748 -Blue Diamond 10780 -Residential (1 Tenant) -Stehower Landscape Centre Designer 10790 -Residential (2 Tenants) 10800 -Residential (1 Tenant) -Demelis S Construction
Germana Place (56-101)	-Street Not Listed
84 Malmo Court	-Blakelock KH Disposal Services -Fiedler Technology Ltd -The Fluid Recycling Mobile Service -Harvester Place Inc -Iveco Equipment -Joe Pace & Son Contracting Ltd -Mapletown Automotive Inc -Pedovani Guido Painting Contractors -Precision Plumbing & Heating Ltd -R&W Maintenance Ltd -Suburban Food Services Ltd -Surburban Water Distributors Inc

	-Vaughan Collision
Rodinea Road (21-99)	21-TTS Systems 45-Advanced Laminated Components -Clearway Construction Inc -DCL Co Inc -Gilbat Metals Ltd -J&M Auto Service -Silvio Construction Co Ltd -Teston Pipeline -Tonys Heavy Equipment Repairs Ltd 67-Asbury Mechanical Services -Doors & More By DDR Ltd -Lualco Steel Erection & Mechanical Services -Mighty Clean Products Inc -Nucorp Products 75-Automatic Apartment Compactors Ltd 99-Marlex Dimensional -Wood Products Ltd

PROJECT NUMBER: 22090200347	
Site Address:	Phase I ESA - Teston Rd, Vaughan, Ontario
Year: 1985	

Site Listing:	-No Site Civic Address Identified
Adjacent Properties:	
Teston Road (1500-2190)	-Street Not Listed
Dufferin Street (10500-10800)	10520-Honeypot Ranch -Residential (1 Tenant) 10748 -Residential (2 Tenants) 10780-Stehower Landscape Contractor Designer -Residential (1 Tenant) 10800-De Melis S Construction -Residential (1 Tenant)
Germana Place (56-101)	-Street Not Listed
84 Malmo Court	-Allsorts Imports Inc -Coombs N Construction Ltd -Dafoe Floor Ltd -Maple Le Car Shop Ltd -Padovani Guido Painting Contractors Ltd -Rockport Enterprises Ltd -Surburban Food Services Ltd -Toronto Reefer Container Service Ltd
Rodinea Road (21-99)	45-Advanced Laminated Components

	<ul style="list-style-type: none"> -Arrow Aluminum -Canadian Conduit & Cable Constructors Inc -Clearway Construction Ltd -J&M Auto Service -Teston Pipeline -Tony's Heavy Equipment Repairs Ltd -Residential (1 Tenant) 67-Bateman Charles Ltd -Lualco Steel Erection & Mechanical Services Ltd -Mighty Clean Products Inc -Rob Stead Stairways -Residential (1 Tenant) 75-Automatic Apartment Compactors Ltd 99-Maplex Dimensional Wood Products Ltd -Stall Master
--	--

PROJECT NUMBER: 22090200347	
Site Address:	Phase I ESA - Teston Rd, Vaughan, Ontario
Year: 1979	
Site Listing:	-No Site Civic Address Identified
Adjacent Properties:	

Teston Road (1500-2190)	-Street Not Listed
Dufferin Street (10500-10800)	10520 -Residential (1 Tenant) 10720 -Residential (1 Tenant) 10748 -Residential (1 Tenant) 10780 -Residential (1 Tenant)
Germana Place (56-101)	-Street Not Listed
84 Malmo Court	-Street Not Listed
Rodinea Road (21-99)	-Street Not Listed

PROJECT NUMBER: 22090200347	
Site Address:	Phase I ESA - Teston Rd, Vaughan, Ontario
Year: 1975	
Site Listing:	-No Site Civic Address Identified
Adjacent Properties:	
Teston Road (1500-2190)	-Street Not Listed

Dufferin Street (10500-10800)	10748 -Residential (1 Tenant)
Germana Place (56-101)	-Street Not Listed
84 Malmo Court	-Street Not Listed
Rodinea Road (21-99)	-Street Not Listed

PROJECT NUMBER: 22090200347	
Site Address:	Phase I ESA - Teston Rd, Vaughan, Ontario
Year: 1970/71	
Site Listing:	-No Site Civic Address Identified
Adjacent Properties:	
Teston Road (1500-2190)	-Street Not Listed
Dufferin Street (10500-10800)	-No Listings Within Radius
Germana Place (56-101)	-Street Not Listed
84 Malmo Court	-Street Not Listed

Rodinea Road (21-99)	-Street Not Listed
-----------------------------	--------------------

PROJECT NUMBER: 22090200347	
Site Address:	Phase I ESA - Teston Rd, Vaughan, Ontario
Year: 1966	
Site Listing:	-No Site Civic Address Identified
Adjacent Properties:	
Teston Road (1500-2190)	-Street Not Listed
Dufferin Street (10500-10800)	-Street Not Listed
Germana Place (56-101)	-Street Not Listed
84 Malmo Court	-Street Not Listed
Rodinea Road (21-99)	-Street Not Listed

PROJECT NUMBER: 22090200347	
Site Address:	Phase I ESA - Teston Rd, Vaughan, Ontario

Year: 1960	
Site Listing:	-No Site Civic Address Identified
Adjacent Properties:	
Teston Road (1500-2190)	-Street Not Listed
Dufferin Street (10500-10800)	-Street Not Listed
Germana Place (56-101)	-Street Not Listed
84 Malmo Court	-Street Not Listed
Rodinea Road (21-99)	-Street Not Listed

-All listings for businesses were listed as they are in the city directory.

-Listings that are residential are listed as “residential” with the number of tenants. The name of the residential tenant is not listed in the above city directory.

APPENDIX E: REGULATORY RECORDS AND REQUESTS



Ali Sultan

From: Public Information Services <publicinformationsservices@tssa.org>
Sent: Thursday, April 6, 2023 2:01 PM
To: Ali Sultan
Subject: RE: Request for Information

You don't often get email from publicinformationsservices@tssa.org. [Learn why this is important](#)

Please refrain from sending documents to head office. The Public Information (PI) team works remotely, mailing in applications will lengthen the overall processing time.

NO RECORD FOUND IN CURRENT DATABASE

Hello,

Thank you for your request for confirmation of public information. TSSA has performed a preliminary search of TSSA's current database.

- We confirm that there are no records in our current database of any fuel storage tanks at the subject address(es).

This is not a confirmation that there are no records in the archives. For a further search in our archives, please submit an application for release of public information (PI Form) through TSSA's new Service Prepayment Portal. The associated fee must be paid via credit card (Visa or MasterCard) through a secure site.

Please follow the steps below to access the new application(s) and Service Prepayment Portal:

1. Click [Release of Public Information - TSSA](#) - TSSA and click "need a copy of a document";
2. Select the appropriate application, download it and complete it in full; and
3. Proceed to page 3 of the application and click the link TSSA Service Prepayment Portal under payment options (the link will take you the secure site to pay for the release via credit card).

Accessing the Service Prepayment Portal:

1. Select new or existing customer (*if you are an existing customer, you will need your account # & postal code to access your account);
2. Select the program area: AD (Amusement Devices), BPV (Boilers and Pressure Vessels), ED (Elevating Devices), FS (Fuels Services), OE (Operating Engineers) or SKI (Ski Lifts) and click continue;
3. Enter the application form number (obtained from bottom left corner of application form) and click continue;
 - a. When selecting the application form number from the drop-down menu, please make sure you select the application that begins with "PI" (i.e. PI-FS, PI-BPV etc.);
4. Complete the primary contact information section;
5. Complete the fees section;
6. Upload your completed application; and
7. Upload supporting documents (if required) and click continue.

Once all steps have been successfully completed, you will receive your receipt via email.

Questions? Please contact TSSA's Public Information Release team at publicinformationsservices@tssa.org.

Although TSSA believes the information provided pursuant to your request is accurate, please note that TSSA does not warrant this information in any way whatsoever.

Kind Regards,



Nicola Carty | Public Information Agent

Public Information

345 Carlingview Drive

Toronto, Ontario M9W 6N9

Tel: +1 416-734-3221 | E-Mail: ncarty@tssa.org

www.tssa.org



Winner of 2022 5-Star Safety Cultures Award

From: Ali Sultan <ASultan@morrisonhershfield.com>

Sent: Wednesday, April 5, 2023 5:01 PM

To: Public Information Services <publicinformationservices@tssa.org>

Subject: Request for Information

[CAUTION]: This email originated outside the organisation.

Please do not click links or open attachments unless you recognise the source of this email and know the content is safe.

Hello,

Do you have any records/information in your databases pertaining to historical and current fuel tanks and associated piping for the properties stated below?

- 2270 Teston Road, Maple, Ontario
- 2400 Teston Road, Maple, Ontario
- 2190 Teston Road, Maple, Ontario
- 21 Rodinea Road, Maple, Ontario
- City of Vaughan Landfill, Maple Ontario (Parcel ID 156720, based on York Region Maps), (Concession 3, Lot 26, Vaughan City, Regional Municipality of York)
- Keele Valley Landfill, 7 Eaglet Court, Maple, Ontario (231740, based on York Region Maps) (Concession 3, Part of Lot 22, 23, 24 and 25, Vaughan City, Regional Municipality of York)
- 1600 Teston Road, Maple, Ontario
- 10500 Dufferin Street, Maple, Ontario

Feel free to contact me if further information is required.

Thank you,

Ali Sultan M.Sc., EIT

Environmental EIT

M +1-647-674-3087

asultan@morrisonhershfield.com



Suite 300, 125 Commerce Valley Drive West | Markham, ON L3T 7W4

Tel: +1-416-499-3110

www.morrisonhershfield.com

People . Culture . Capabilities

 *Please consider the environment before printing this email.*

This electronic message and any attached documents are intended only for the named recipients. This communication from the Technical Standards and Safety Authority may contain information that is privileged, confidential or otherwise protected from disclosure and it must not be disclosed, copied, forwarded or distributed without authorization. If you have received this message in error, please notify the sender immediately and delete the original message.

Ministry of Public and Business Service Delivery

Access or Correction Request

Freedom of Information and Protection of Privacy Act

Personal information contained on this form is collected under the *Freedom of Information and Protection of Privacy Act* and will be used to answer your request.

Questions about this collection should be directed to the Freedom of Information and Privacy Coordinator at the institution where you make the request.

Many records of public institutions are available to you without making a request under the *Freedom of Information and Protection of Privacy Act*. Contact the Freedom of Information and Privacy (FOIP) Coordinator at the institution that holds the records to determine whether you need to make a formal request.

Section A - Type of Request

Fields marked with an asterisk (*) are mandatory.

Check the box that indicates what you are requesting. (Records that do not contain personal information are general records.)

The FOIP Coordinator will contact you to verify your identity before giving you access to your own personal information or to secure proof that you have authority to act for another person if making a request for another person's personal information records (e.g., power of attorney, guardian or trusteeship order).

Type of Request *

- Access to general records (non-personal information)
- Access to own personal information
- Access to other's personal information by authorized party
- Correction of own personal information

Name of institution request made to *

Ministry of the Environment, Conservation and Parks

Freedom of Information and Privacy Coordinator Contact

Email Address: foi.mecp@ontario.ca

Telephone Number: 416-314-4075

Section B - Requester's Information

Fields marked with an asterisk (*) are mandatory.

Please ensure you have entered your name, mailing address, telephone and email address accurately.

Last Name *

Sultan

First Name *

Ali

Mailing Address

Canada U.S.A. International

Unit Number

300

Street Number

125

Street Name

Commerce Valley Drive West

PO Box

City/Town *

Markham

Province *

ON

Postal Code *

L3T 7W4

Telephone Number

Home

Mobile

Business

647-674-3087

ext.

Email Address *

asultan@morrisonhershfield.com

Section C - Description of Records or Correction Requested

Fields marked with an asterisk (*) are mandatory.

Provide as much detail as possible about the requested general records, own personal information, other's personal information or correction of own personal information.

If you are requesting access to personal information, provide the name that appears on the records.

If you are requesting a correction of your own personal information, describe the personal information to be corrected. The Ministry of Environment, Conservation and Parks will contact you with next steps in the process.

Description of Records or Correction Requested *

The description of records or correction that you entered for this FOI eRequest has been removed for the purposes of this email to protect the security of any personal information that may have been included.

The institution that you selected has received the complete copy of the FOI eRequest inclusive of contents you entered in this field.

Time Period of the Records *

Specify the time period for the records as precisely as possible, e.g., from 2008/07/21 to 2009/11/30.

From (yyyy/mm/dd)

To (yyyy/mm/dd)

1970/01/01

2023/04/05

Method of Access *

Check a box to indicate whether you want to examine original documents (which may only be done on site) or receive copies.

Receive copy

Examine original (on site only)

Payment confirmation number: 25790667

**Ministry of the Environment,
Conservation and Parks**

Access and Privacy Office

12th Floor
40 St. Clair Avenue West
Toronto ON M4V 1M2
Tel: (416) 314-4075

**Ministère de l'Environnement, de la
Protection de la nature et des Parcs**

Bureau de l'accès à l'information et
de la protection de la vie privée

12^e étage
40, avenue St. Clair ouest
Toronto ON M4V 1M2
Tél. : (416) 314-4075



May 5, 2023

Ali Sultan
Morrison Hershfield
300 - 125 Commerce Valley Drive West
Markham, Ontario L3T 7W4
asultan@morrisonhershfield.com

Dear Ali Sultan:

**RE: MECP FOI A-2023-02108, Your Reference #: 20230405175341796 –
Record Release Letter**

This letter is further to your request made pursuant to the Freedom of Information and Protection of Privacy Act (the Act) relating to 10500 Dufferin Street, Maple.

Attached is a copy of the records.

If you have any questions, please contact Sylwia Rynkiewicz at 437-995-1618 or sylwia.rynkiewicz@ontario.ca.

Yours truly,

Sylwia for

Ryan Gunn
Manager (A), Access and Privacy Office

Attachment



Search

Go

Generator Details

Registration/Notification Number

ON6558846

Legal Company Name

Primary Name:	Richview Manor Vaughan Limited Partnership	Division Name:	NA
---------------	--	----------------	----

Company Operating Name

Primary Name:	Richview Manor Vaughan Limited Partnership	Division Name:	NA
---------------	--	----------------	----


Mailing Address

Division Building:	NA	Post Box Number:	NA
Address Line 1:	10500 Dufferin Street	Address Line 2:	NA
Town/City:	Maple	Postal Code / Zip Code:	L6A 4R1
County: (if inside Ontario)	YORK (R. M.)	Province/State (If inside Canada/US)	ONTARIO
County: (if outside Ontario)	NA	Province / State (If outside Canada / US)	NA
Country:	Canada		

Site Location

This should be the street address of the site that is being registered. You are required to register each site that generates hazardous waste separately.

Division Building:	NA	Post Box Number:	NA
Address Line 1:	10500 Dufferin Street		
Address Line 2:	NA		
Town/City:	Maple	Postal Code / Zip Code:	L6A 4R1
County: (if inside Ontario)	YORK (R. M.)	Province / State (If inside Canada / US)	ONTARIO
County: (if outside Ontario)	NA	Province / State (If outside Canada / US)	NA
Country:	Canada		



Company Name: **Richview Manor Vaughan Limited Partnership**
Company Number: **ON6558846 (Generator)**

Active Waste Classes

Active Waste Class Listing

[Add New Waste Class](#) | [Inactive waste classes](#)

Active Off-site Waste Classes

Waste Class	View Details	Hazardous Waste Number (per waste stream)	Reg. 347 Schedules	Disposal Method	Part 2B required	Part 2B complete	Physical State	Off-Site	Status	UnRegister Waste Class
251 - L	View Details	N/A					Liquid	Off-Site	Active	

Back

APPENDIX F: AERIAL PHOTOGRAPHS



1956

Teston Road

Keele Street

Dufferin Street


Major Mackenzie Drive West



1964

Dufferin Street


Teston Road



Teston Road

Dufferin Street

Major Mackenzie Drive West



1: 9,028
March 29, 2023



Notes

This map was printed from a YorkMaps application.

2002 Aerial Photograph

Legend

- Site Boundary



DEEP IN I.T.

53

Pardes Shalom Cemetery

Germana Pl

Vaughan Fire Station 7-10

49

Teston Rd

Richview Manor

53

Goldenview Ct


Lady Fenrose Ave



2016 Aerial Photograph

Legend

- Site Boundary



DEEP IN I.T

53

Pardes Shalom Cemetery

Gemana Pl

Vaughan Fire Station 7-10

49

Teston Rd

Richview Manor

53

Goldenview Ct


Lady Fenrose Ave



2022 Aerial Photograph

Legend

- Site Boundary



1000 ft

APPENDIX G: SITE PHOTOGRAPHS





Photo 1: View of the Site facing south-southeast



Photo 2: View of the Site facing west



Photo 3: View of the Site, facing east



Photo 4: View of north adjacent property, facing south-southwest



Photo 5: View of southeast neighboring properties and Dufferin Street, facing south



Photo 6: View of west neighboring properties, facing west




Photo 7: View of south neighboring properties, facing northwest



Photo 8: View of northeast neighboring properties, facing north